



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 27, 2012

Reviewed: *PBB*

Mine Name: Jumbo-Jensen Quarry	Permit Number: M/041/0008
Operator Name: United States Gypsum Company	Inspection Date: November 1, 2011
Inspector(s): Peter Brinton, Lynn Kunzler	Time: 2:00pm to about 3:30pm
Other Participants: Jeremy Taylor, US Gypsum	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Earthwork (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit fee: Current

Bond Renewal Date: Adjustment in progress

Bond Amount: \$372,300

Purposes of Inspection: To inspect areas recontoured in 2011

Inspection Summary:

Parts of two recontoured areas (the Claw and 4A SE) were inspected. The recontouring work at 4A SE was found acceptable, and the Claw area needed additional dozer work near the crest of the slope. Characteristics of acceptable reclamation earthwork in this environment were discussed, including the need to minimize potential rockfall hazards while simultaneously maintaining equipment operator safety.

Limited revegetation inspection was also done of area J45, which was seeded in 2010. Some beneficial vegetation was observed, as well as weedy species in the area. The need for closer inspection and possible future mining plans of areas C5 and C7 were discussed, and it was determined that these areas would not be released at this time. Additional inspection will be made by the Division when requested.

Conclusions and Recommendations:

It is recommended that the Division partially release area 4A SE.

Inspector's Signature

Peter Brinton

PNB: pbb; eb

cc: Bruce Allen, United States Gypsum Company

O:\M041-Sevier\M0410008-JumboJensen\inspections\Insp-11012011.doc



Inspection Date: November 1, 2011

Page 2 of 2

M/041/0008



Acceptable recontouring of 4A SE (Stitched photo).